## **MEMORANDUM**

SUBJECT: Trip Report – Westlake Landfill Site, 13570 St. Charles Rock Road, St. Louis, Missouri

CERCLIS ID: MOD079900932; SSID: 0714

FROM: Kevin Larson, On-Scene Coordinator

Emergency Response and Removal North Branch

THRU: Dan Gravatt, Remedial Project Manager

Missouri/Kansas Remedial Branch

TO: Cecilia Tapia, Director

**Superfund Division** 

## OSC oversight December 19-21, 2013:

December 19, 2013, Thursday: OSC Larson on-site with electrician. The electrician installed electrical connections for the two Radeco air samplers that will be arriving on-site Friday, December 20, 2013.

December 20, 2013, Friday: EPA OSC Larson met with Paul Eastvold of Feezor Engineering on-site. The housings for the two Radeco air samplers were delivered on-site and placed at two locations; one near the office trailer and the other adjacent to the transfer facility. GPS coordinates for the two Radeco air sampler units are as follows: transfer station location: N 38 46' 09", W 90 26' 39"; for the office trailer location N38 46' 10", W 90 26' 30".

Following the placement and testing of the two Radeco air sampler units, personnel conducted an over land gamma survey of the area between the transfer station and the Site boundary fence. The survey used a GPS data logging system.

December 21, 2013, Saturday: OSC Larson returned to Kansas City.

There will be no on-site activity until the week of January 6, 2014.

To my knowledge, the site was not visited by the general public or any media outlets during this time period. No visible emissions of dust were observed from activities being conducted by this project.

All site photographs, drawings, records and/or other actions taken that document EPA OSC oversight or PRP actions can be found at: www.epaosc.org/westlakeoversightinfo.

4110

40436690 30 Superfund

audi

**MOKS** 

H:\SUPR\MOKS\Gravatt\2014\westlake trip report – krell 20140109.doc

**ERNB** Larson

**MOKS** 

**CNSL** Asher

**ENSV** Hammerschmidt

Field

SUPR Jackson **SUPR**